Section No.	Street Name	Segment	Estimated Street Segment Length	Comments/Notes			
Baseline R	Baseline Rehabilitation Work- Street Segments with minimal subsurface concerns						
2270	Orange Street	Front St-Ann St	625	Granted funded project to repair/replace utilities, construct permeable pavement parking aisle, and reconstruct remainder of standard paving to be made part of larger overall Phase 1 Street Rehabilitation project			
2720	Pollock St	Cedar St-Pine St	480				
2730	Pollock St	Pine St-Mulberry St	505				
2740	Pollock St	Mulberry St-End	188				
2210	Gordon St	Broad St-Cedar St	487				
1830	Hedrick St	Pine St-Craven Ave	481				
1700	Island View Dr	Front St-Loop	1346				
1590	Laurel Ln	Lennoxville Rd-S End	923				
1840	Craven Ave	Hedrick St-First St	315				
1990	Safrit Dr	Lennoxville Rd-N of Lennoxville Rd	800				
1690	Jefferson St	Lennoxville Rd-Loop	2655				
860	Ricks Ave	Third St-Sherwood Blvd	450	Rehab of only part of street needed. Length is from south of Beau Coast future entrance to edge of Sherwood. <i>Measure in field</i>			

Section No.	Street Name	Segment	Estimated Street Segment Length	Comments/Notes	
450	Eastern Ave	Wellons Dr-N End	544		
1340	Stanton Rd	S End-Atlantic Dr	395		
1350	Stanton Rd	Atlantic Dr-W Beaufort Rd	333		
1360	Stanton Rd	W Beaufort Rd-N End	774		
1330	Olivia Rd	Angela Rd-W End	735		
Baseline Street Construction Work - Construction of new pavement at currently unpaved streets					
	Howard Jr Lane	Fairview Dr - Center St	400		
	Well Access Dr	Live Oak St-Town Property Line	380		
Tentatively included Street Segments - Street Segments with Subsurface Utilities recommended for replacement or examination but with no to minimal observable signs of Utility-caused Street Issues (i.e. Recent Patches, Subsidence, Sinkholes, Etc.)					
360	Professional Pk Dr	Tradd St-Meeting St	365	2010 SESS recommendation for rehabilitation of MH @ Tradd	
370	Professional Pk Dr	Meeting St-Troon Way	370		
380	Professional Pk Dr	Troon Way-Courtyard East	322		
390	Professional Pk Dr	Courtyard East-Hwy 70	1515	Point repair of sanitary gravity sewer needed prior to street paving	
2550	Craven St	Pine St-Mulberry St	999	Sinking adjacent to catch basin : With repair could proceed with street. 4" cast iron waterline in street.	

Section No.	Street Name	Segment	Estimated Street Segment Length	Comments/Notes
2700	Pollock St	Ann St-Broad St	1031	6" cast iron water line in street; however, no signs of utility issues.
2770	Marsh St	Broad St-Cedar St	1012	8" truss sewer pipe in street; however, no signs of utility issues. 2010 SESS recommendation for MH repair @ Broad.
2780	Marsh St	Cedar St-Pine St	1012	8" truss sewer pipe in street; however, no signs of utility issues. 2010 SESS recommendation for MH repair <u>in</u> Cedar.
2790	Marsh St	Pine St-Mulberry St	1007	8" truss sewer pipe in street; however, no signs of utility issues.
730	Live Oak	Front St-Ann St	1217	No suspect utilities; however, waterline upsize recommended by master plan.
750	Live Oak St	Broad St-Cedar St	1002	6" cast iron water line in street but utility patches are along centerline of street are older and neat.
1820	Hedrick St	Cedar St-Pine St	1020	6" cast iron waterline reported but may have been replaced. 2010 SESS recommendation for MH rehabilitation.
850	Carteret Ave	Willow St-Third St	460	2010 SESS recommendation for MH repair.
1710	Taylors Creek Rd	Front St-N End	721	8" sewer truss pipe; however, reportly located outside of street. Depression bordering gutter @ 2211.
1260	Sherwood Blvd	Ricks Ave-George St (West End)	290	2010 SESS recommendation for MH rehabilitation & inspection of sewer; however, sewer is reportedly lined. (This leg called Ricks Ave by Stantec draft report.)
870	Sherwood Blvd	Ricks Ave-112 ft E of Ricks Ave	1125	2010 SESS recommendation for MH rehabilitation & inspection of sewer; however, of 3 runs of sewer is reportedly lined.
880	Sherwood Blvd	112 ft E of Ricks Ave-George St (East End)		
240	Campen Rd	Live Oak St-Lockhart Dr	90	8" vitrified clay pipe with 2010 SESS recommendation for TV inspection -tentaively selected pending TV inspection. (Begin work at end of NCDOT resurfacing.)

Section No.	Street Name	Segment	Estimated Street Segment Length	Comments/Notes
250	Campen Rd	Lockhart Dr-Wellons Dr	215	8" sewer truss pipe; however, sewer is reportedly deep and no issues have reportedly been experienced.
440	Mashburn Dr	Glenda Dr-Pinners Point Road	Xhh	8" sewer truss pipe; however, sewer is reportedly deep and no issues have reportedly been experienced. <i>Check of strmwtr pipe crossing needed.</i>
1270	Joyce Blvd	W Beaufort Rd-Ronnie Rd	594	Summer 2018 pipe repair due to sinking MH @ corner of Joyce & Ronnie. <i>Recheck of MH needed.</i>